

312 BG Premium Full Synthetic ATF

APPLICATION CHART

BG Premium Full Synthetic ATF, PN 312, meets or exceeds the performance requirements of the following automatic transmission fluids.

MAKE	ATF PN
Acura	ATF-Z1, DW-1, TYPE 2.0 08200-9015(A), TYPE 3.0 08200-9016(A), TYPE 3.1 08200-9017(A)
Aisin Warner	AW-1, AS69RC, 05189966AB, 05189977AA
Alfa Romeo	ALL
Allison	C-3, C-4, John Deere HD SynTran, TM Mobil Delvac Synthetic ATF TM
American Motors	ATF +3 (MS-7176E), +4 (MS-9602)
Aston Martin	ALL
Audi	G052025A2, G052162A1, G052162A2, LT71141, G055025A2, G055005A2, G055162A2, G060162A2, G055005A6, G052990A2, G055540A2
Bentley	PY112995PA
BMW	LA2634, LT71141, 81229400275, 83220142156, 83220403248, 83220403249, 83229407765, 83229407807, 83220024359, 83220026922, BMW807, TEXACO ETL-7045E, TEXACO ETL-8072B, 83220142516, 705/ATFD-3, 83220402413, 83220397114, 83222152426, 83227542290, 83222163514, 83222220442, 83222220445, 83222289720, 83222355599, 83222220443, 83222305396, 83220144137, 83222305395, 83222220438
Caterpillar	TO-2
Chrysler/Mopar	ATF 7176, +2, +3 (MS-7176E), +4 (MS-9602), AS68RC, AS69RC, 05127382AB, 05189966AB, 05189966AA, 05189977AA, 05189977AB, 05127382AA, 68157995AA, 68157995AB, 68218925AA, 68171866, 68171869AB, 68218925AB, 68333587AA, 68218057AC
Citroen	973622, Z000169756, AL-4
Daewoo	LT71141
Daihatsu	AMMIX ATF-DII, AMMIX ATF-DIII
Diwa	55.6335.XX (G607), 55.6336.XX (G1363)
Esso	ATF LT 71141
Fiat-Lancia	ALL
Ford	MERCON [®] (XT-2-QDR OR XT-2-QSM), MERCON [®] SP (XT-6-QSP), MERCON [®] V (XT-5-QM), MERCON [®] LV (XT-10-QLVC), PREMIUM AUTOMATIC TRANSMISSION FLUID (XT-8-QAW), FNR5 AUTOMATIC TRANSMISSION FLUID (XT-9-QMM5), XT-2-QDX
Fuchs	Titan ATF 3292, Titan ATF 3353, Titan ATF 4134
Fuso	ATF-II, ATF-SPIII
General Motors	DEXRON [®] , DEXRON [®] -II, -IID, -IIE, -III, -IIIG/H, DEXRON [®] -VI, GM T-IV (PN 88900925), 9986195, Type A Suffix A (TASA), 22717466, 93160393
Honda	ATF-Z1, DW-1, TYPE 2.0 08200-9015(A), TYPE 3.0 08200-9016(A), TYPE 3.1 08200-9017(A)
Hyundai	SP-II, SP-III, SPH-IV (00232-19045), 040000C90SG, NWS-9638, SPH-IV-RR, 00232-19012, 00232-19015, 00232-19016, 00232-19023, 00232-19024, SP4-M, JWS-3309 T-4, 00232-19057, 00232-19059, NWS-9638 T5, 00232-19052
Idemitsu	K17, JATCO 3100 PL085, W0133-19031-54
Infiniti	MATIC D, J, K, S, 402
Isuzu	ATF-II, ATF-III, ATF-SP, 08200-9001
Jaguar	ATF 3403 M115, C2C8432, 1X43 2C9010AA, JLM 20237, JLM 20238, JLM

	20292, LT71141, JATCO 3100 PL085, JDE 26444
JASO	1A
Jeep	SEE CHRYSLER/MOPAR
JWS	3309, 3314, 3317, 3324
Kia	SP-II, SP-III, RED 1, SP IV, UM090-CH042 (TYPE 4 SP-IV), ATF TYPE 4(M)
Land Rover	ESSO LT71141, TEXACO N402, TYK500050, LRN 13754, TEXACO ETL-7045E, STC 4863, STC 505.31, LR 002748, LR 023288, LR 023289, JDE 26444
Lexus	TYPE T, T-II, T-III, T-IV, WS
Man	339F, 339V1, 339V2, 339Z1, 339Z2, 339Z3
Maserati	231603
Matra	ALL
Mazda	ATF-M III, ATF-MV, ATF-FZ, 0000-77-112E-01, 0000-77-120E-05, 0000-77-114E-01, 0000-FZ-113E-01
Mercedes Benz	236.1, 236.2, 236.3, 236.5, 236.6, 236.7, 236.8, 236.9, 236.10, 236.11, 236.12, 236.14, 236.41, 236.81, 0019892103, SHELL 3403-4 115, A0019892203, 0019894503, ATF 4134, 0019896803
Mitsubishi	DIAMOND SP, SP-II, SP-III, SP-IV, J2, J3
Nissan	MATIC D, J, K, S, 402
Opel	1940700, 1940767, 1940771, 2217466, 88900925, 9986195
Peugeot	973622, Z000169756, AL-4
Porsche	999 917 547 00A2, 000 043 205 09, 000 043 204 41, SHELL 3403 M115, 999 917 547 00, 000 043 205 28, 000 043 306 24, 958 300 540 00, Z 000 169 756
Renault	7711218368, DPO
Rolls Royce	PL31493 PA
Saab	93160372, 93160393, 93165147
Saturn	22689186
Shell	LA2634, ATF 3353, ATF 3403 M115, M-1375.4, M-1375.5, M-1375.6, M-L12108
Subaru	SOA868V9240, SOA868V9241, K0140Y0700, ATF-HP, HP/PS SOA427V1500
Suzuki	99980-06000, ATF 3317 SP-4B, 990B0B-01001, 3314
Texaco	ETL-7045E, ETL-8072B, N402
Toyota	TYPE T, T-II, T-III, TYPE T-IV, TOYOTA WS
Voith	55.6335.XX (G607), 55.6336.XX (G1363)
Volvo	97325, 97335, 97340, 97341, 97342, 3344208, 31256774, 31256775, 31256776, 1161521, 1161540, 1161640, 1161621
Volkswagen	G055025A2, G055162A2, G052162A2, G052990A2, G052025A2, G052162A1, G055005A6, LT71141, G055005A2, G060162A2, G055540A2
ZF Friedrichshafen AG	TE-ML: 02F, 03D, 04D, 05L, 09, 11A, 11B, 14A, 14B, 14C, 16L, 17C, 20B, 21L; SHELL LA 2634, LT 71141, LifeGuard Fluid 6 (S671090255), LifeGuard Fluid 6 Plus (S671090281), LifeGuard Fluid 8 (AA00601304, S671090312), LifeGuard Fluid 9

BG Universal Synthetic ATF is not recommended for use in the following applications:

- Continuously Variable Transmissions (CVTs)
- Dual Clutch Transmissions (DCT)
- Direct-Shift Gearbox (DSG)
- Ford Type F, Motorcraft® MERCON® ULV (XT-12-QULV)
- AC Delco® DEXRON® ULV PN 10-4107, GM DEXRON®-HP
- All Mercedes Benz 722.9 transmissions built after June 21, 2010 requiring ATF A0019897803 (236.15), A001989770309

BG Products, Inc., accepts no liability for excessive use or misuse of this product.

Revision date 8-19-21

Revisions **Removed from Acura section**

- PN

Added to BMW section

- 83222220438

Added to Chrysler/Mopar section

- 05189977AB

Edited in Ford section

- ADDED SPACING AFTER (®)

Added to Fuso section

- ADDED "SP", NOW READS ATF-SPIII

Added to Honda section

- TYPE 3.0 08200-9016(A)

- REMOVED PN

- ADDED (A)

Added to Land Rover section

- JDE 26444

Added to Porsche section

- Z 000 169 756

Edited in "Not Recommended" section

- REMOVED PN XT 12QULV

- ADDED (XT-12-QULV)

3-23-21 Updated BMW section

- 83222220442, 83220144137, 83222305395

Updated Chrysler/Mopar section

- 68333587AA, 68218057AC

6-9-20 Updated "Not Recommended" section

- ADDED "MOTORCRAFT® MERCON® ULV, PN XT12QULV"

- ADDED "AC DELCO® DEXRON® ULV, PN 10-4107"

4-24-20 Updated on Chrysler/Mopar section

- 05189977AB

- 68171866AB

2-21-20 Updated on Ford section

- "XT-10-QLV" TO "XT-10-QLVC"

1-13-20 Added to Chrysler/Mopar section

- 68218925AB

8-19-19 Edited in Lexus section

- NS to WS

Edited in BMW section

- 8322222043 to 83222220443

8-7-19 Added to American Motors section

- ATF +3 (MS-7176E), +4 (MS-9602)

Removed from Bentley

- ALL INCLUDING

Edits in BMW

- Corrected ETL (Was ELT)
- Removed (1375.4)
- Added 8322222043, 83222305396

Added in Citroen

- AL-4

Removed in Daewoo

- ALL INCLUDING

Added NEW Daihatsu section

- AMMIX ATF-DII, AMMIX ATF-DIII

Edits to Diwa section

- Removed ALL
- Added 55.6335.XX (G607), 55.6336.XX (G1363)

Added to Fuchs section

- Titan ATF 4134

Added NEW Fuso section

- ATF-II, ATF-III

Added in General Motors

- TYPE A Suffix A (TASA), 22717466, 93160393

Added in Honda

- TYPE 2.0 08200-9015

Added in Hyundai

- 00232-19052

Edits in Infiniti

- Removed ALL INCLUDING
- Added 402

Edits in Isuzu

- Removed ALL
- Added ATF-II, ATF III, ATF-SP, 08200-9001

Added in Jaguar

- JLM 20292

Edits in Lexus

- Removed ALL
- Added Type T, T-II, T-III, T-IV, WS

Edits in Opel

- Removed ALL
- Added 1940700, 1940767, 1940771, 2217466, 88900925, 9986195

Added in Peugeot

- AL-4

Added in Renault

- DPO

Removed in Saturn

- ALL

Edits in Subaru

- Added SOA868V9240
- Removed (HP), ALL

Removed in Suzuki

- Removed ALL

Added in Volvo

- 97325, 97335

Added in ZF Friedrichshafen AG

- 21L

11-30-18 Added to Porsche section

- 000 043 306 24, 958 300 540 00

7-9-18 Added to “Not recommended” section

- MERCEDES BENZ A001989770309

5-7-18 Updated NAME

- CHANGED FROM BG UNIVERSAL SYNTHETIC ATF TO BG PREMIUM FULL SYNTHETIC ATF

Updated PN in Ford section

- CHANGED FROM X-2-QDX TO XT-2-QDX

4-18-18 Added to BMW section

- 83222355599

2-27-18 Added to ZF section

- LifeGuard Fluid 9

10-23-17 Added to ZF section

- TE-ML 20B

9-13-17 Added to “Not recommended for use in the following applications” section

- Ford MERCON® ULV, XT-12-QULV

Added to Honda section

- 08200-9015

4-4-17 Added to BMW section

- 83222289720

1-19-17 Added to Land Rover section

- LR 023289

12-9-16 Revised Ford and GM sections

- Removed spaces after MERCON®

- Added hyphens after DEXRON®

10-20-16 Added to Acura

- TYPE 3.1 PN 08200-9017A

8-23-16 Added to Acura

- TYPE 2.0 PN 082009015A

5-5-16 Added to Not Recommended section

- GM Dexron HP

4-28-16 Added to Land Rover:

- LR 023288

3-17-16 Added to Chrysler/Mopar:

- 68171869AB

Added to Honda:

- TYPE 3.1 08200-9017

1-25-16 Added to Aisin Warner

- AS69RC, 05189966AB, 05189977AA

Added to Chrysler/Mopar

- AS69RC, 05189966AB

1-5-16 Added to Acura

- TYPE 3.0 PN 08200-9016A

Added to BMW

- 83222220445 (1375.4)

7-20-15 Added to Land Rover:

- LR 023288

7-13-15 Changed Acura:

- REMOVED "ALL" ADDED "ATF-Z1, DW-1"

Added to Fuchs:

- Titan ATF 3353

Added to Hyundai:

- 00232-19057, 00232-19059

Removed from Hyundai:

- T-5

Added to Mercedes Benz:

- 236.41, 236.81

6-25-15 Added to Allison:

- John Deere HD SynTran™

- Mobil Delvac Synthetic ATF™

5-18-15 Added this PN to Chrysler/Mopar:

- 68171866

3-27-15 Added this PN to Kia:

- ATF TYPE 4(M)

**3-9-15 Added "(S671090312)" to LifeGuard Fluid 8
under ZF Friedrichshafen AG**

10-28-14 Removed "ALL" from Jeep. Replaced with:

- See Chrysler/Mopar

10-1-14 Added this ATF PN from Chrysler/Mopar:

- 68218925AA

Added this ATF PN from Fuchs:

- Titan ATF 3292

9-3-14 Removed these ATF PN's from Allison:

- TES-295

- TES-389

8-28-14 Added these ATF PN's to Volvo:

- 31256775

- 31256776

8-13-14 Added these ATF PN's to Mazda:

- ATF-FZ

- 0000-FZ-113E-01

6-12-14 Added this ATF PN to Subaru:
- HP/PS (SOA427V1500 HP)