

315 BG Low Viscosity Full Synthetic ATF

APPLICATION CHART

BG Low Viscosity Full Synthetic ATF, PN 315, meets or exceeds the performance requirements of the following automatic transmission fluids.

MAKE	ATF PN
Acura	DW-1, TYPE 2.0 08200-9015(A), TYPE 3.0 08200-9016(A), TYPE 3.1 08200-9017(A)
Aisin Warner	AW-1
Audi	G 052 540, G 055 005/A2/A6, G 055 162/A2, G 060 162, G 055 540/A2
BMW	83 22 0 142 156, 83 22 0 142 516, 83 22 0 144 137, 83 22 2 152 426, 83 22 2 305 396, 83 22 2 220 443, 83 22 2 305 397, 83 22 2 355 599, 83 22 2 289 720, 83 22 0 397 114, 83 22 2 163 514, 83 22 2 220 445, 83 22 0 024 359, 83 22 0 403 249
Chrysler/Mopar	68043742AA, 68043742AB, 68065322AA, 68157995AA, 68157995AB, 68218925AA, 68218925AB, 68171866AA, 68171866AB, 68171869AA, 68171869AB, 68339073AA
DSIH	6P805 (GEELY, SSANGYONG, MAHINDRA 6SP)
Ford	MERCON® LV (XT-10-QLVC), MERCON® ULV (XT-12-QULV), MERCON® SP (XT-6-QSP)
GM	DEXRON®-VI, DEXRON® ULV, 88863400, 88863401
Honda	DW-1, TYPE 2.0 08200-9015(A), TYPE 3.0 08200-9016(A), TYPE 3.1 08200-9017(A)
Hyundai/Kia	SP-IV, SPH-IV, SP-IV-RR, NWS-9638, 040000C90SG, SP4-M, UM090-CH042 (TYPE 4 SP-IV), ATF TYPE 4 (M)
Infiniti	MATIC-S
Isuzu	SCS 2-90531-200-0
Jaguar	JDE 26444, C2C8432
JASO	1-A-LV
JWS	3324
Land Rover	JDE 26444, LR 023288, LR 023289, TYK500050, LRN 13754
Lexus	WS
Mazda	ATF-FZ (0000-FZ-113E-01)
Mercedes-Benz	236.12, 236.14, 236.15, 236.16, 236.17, 236.41, A0019896803, A0019894503, A0019897803, ATF 4134
Mitsubishi	ATF-J3, ATF-MA-1, ATF-PA, SP-IV
Nissan	MATIC-S
Porsche	000 043 306 24, 000 043 210 54, 958 300 540 00
Saab	93160372
Shell	M-L12108, ATF 134, ATF 134FE, ATF 3353, ATF 97, ATF D971, M-1375.4, M-1375.6
Toyota	WS (JWS 3324)
Volvo	97342, 31256774, 31256775, 31256776
VW	G 052 540, G 055 005, G 055 162, G 060 162, G 055 540
ZF Friedrichshafen AG	LifeGuard Fluid 6 (S671090255), LifeGuard Fluid 6 Plus (S671090281), LifeGuard Fluid 8 (AA00601304, S671090312), LifeGuard Fluid 9

BG Low Viscosity Full Synthetic ATF is not recommended for use in the following applications:

- Ford Type F
- Continuously Variable Transmissions (CVTs)
- Direct-Shift Gearbox (DSG)
- Dual Clutch Transmissions (DCT)
- GM DEXRON®-HP

BG Products, Inc., accepts no liability for excessive use or misuse of this product.

Revision date 08-19-21

Revisions **Added to Acura section**
- (A)

Added to Audi section
- A2/A6 BEHIND G 055 005
- A2 BEHIND G 055 162, G 060 162, G055 540

Added to Honda section
- (A)

Switched order of sections to display “Infiniti” before “Isuzu”

04-09-21 **Added to Porsche section**
- 000 043 210 54

04-09-21 **Added to Acura section**
- TYPE 2.0 08200-9015

Added to Audi section
- G 055 540

Added to BMW section
- 83220142156, 83222220443

Added to Chrysler/Mopar section
- 68339073AA

Added to Hyundai/Kia section
- UM090-CH042 (TYPE 4 SP-IV), ATF TYPE 4 (M)

Added Infiniti section
- MATIC-S

Added to Land Rover section
- LRN 13754

Added to Mercedes-Benz section
- A0019896803, A0019894503, A0019897803, ATF 4134

Added Saab section
- 93163072

Added Volvo section
- 97342, 31256776

Added VW section
- G 055 540

Added ZF Friedrichshafen AG section
- LifeGuard Fluid 9

01-07-21 **Added to Ford section**

- MERCON® ULV (XT-12-QULV), MERCON® SP (XT-6-QSP)

Added to GM section

- DEXRON® ULV

Added to Honda section

- TYPE 2.0 08200-9015

Added to Mitsubishi section

- ATF-MA-1

Added to Shell section

- ATF 134, ATF 134FE, ATF 3353, ATF D97, ATF D971

Removed from Not Recommended section

- Ford MERCON® ULV, XT-12-QULV, DEXRON® ULV

02-21-20 Added to BMW section

- 83 22 0 144 137, 83 22 2 305 397

Added to Chrysler/Mopar section

- 68218925AB, 68043742AA, 68043742AB, 68065322AA

Added to Not Recommended section

- DEXRON® ULV

11-30-18 Added to Porsche section

- 000 043 306 24, 958 300 540 00

10-12-18 Added to Acura:

-DW-1, TYPE 3.0 08200-9016A

Added to BMW:

-83 22 2 305 396, 83 22 2 355 599, 83 22 2 289 720, 83 22 0 397 114, 83 22
2 163 514,
83 22 2 220 445, 83 22 0 024 359, 83 22 0 403 249

Added to Chrysler/Mopar:

-68218925AA, 68171866AA, 68171866AB, 68171869AA, 68171869AB

Added to GM:

-88863400, 88863401

Added to Honda:

-TYPE 3.0 08200-9016A, TYPE 3.1 08200-9017A

Added to Hyundai/KIA:

-040000C90SG, SP4-M

Added Isuzu:

-SCS 2-90531-200-0

Added Jaguar:

-C2C8432

Added to Land Rover:

-LR 023288, LR 023289, TYK500050

Added Mazda:

-ATF-FZ (0000-FZ-113E-01)

Added Mercedes-Benz:

-236.15, 236.16, 236.17

Changed on Volvo:

- WAS "31256675" UPDATED TO "31256775"

Added to Not Recommended section

- GM DEXRON®-HP

Removed from Not Recommended section

- All Mercedes Benz 722.9 transmissions built after June 21, 2010 requiring ATF A0019897803 (236.15)

12-9-16 Fixed on Ford:
REMOVED SPACE BETWEEN MERCON® AND LV

10-20-16 Added to Acura:
-TYPE 3.1 08200-9017A

11-2-15 Original